

Capri

Produktbeskrivelse



| Produktbeskrivelse | Metoder | Produktdata | |
|------------------------------|---------------------------|-----------------------------|--------------|
| Konstruktion | | | |
| Struktur | ISO 2424 | Vævet loop pile | |
| Luvmateriale | DIR 96/73, 96/74 | 100% polyamid | |
| Farvemethode | - | Forfarvet garn | |
| Bagside | eTL | NL - Naturlatex | |
| Dimensioner | ISO 3018 | Approx. 400 cm | |
| Totalhøjde | eTL | Ca. 3,9 mm. | |
| | . | 0.154''' | |
| Totalvægt | eTL | Ca. 1.900 g/m2 | |
| | . | 56.05 oz./yd2 | |
| Luvindsatsvægt | eTL | 650 g/m2 | |
| | . | 19.175 oz./yd2 | |
| Egnethedsprøvnings | | | |
| Brugsområder | eTL | 32 - Erhverv - Normal brug | |
| Antistatiske egenskaber | eTL | Permanent antistatisk | |
| Gulvvarmeeget | eTL | Ja | |
| Øvrige brugstests | - | Commercial - Heavy | |
| Sikkerhed & Miljø | | | |
| Brandklassifikation | ASTM E-648 | Class 1 | |
| | ASTM E662 Smoke Density | <450 | |
| | ASTM D2859 Surface Flamm. | Pass | |
| | EN 13501-1 Euroclass | Cfl-s1 | |
| | CE Mærkning | EN 14041 | Certificeret |
| | Ydeevnedeklaration DBI | CONTRACT GROUP 15 | |
| | Notified body no. | 2531 | |
| | Ce Year | 16 | |
| | Skridsikkerhed EN 13893 | Class DS | |
| Vejledninger | | | |
| Montering, inkl. limguide | DK | Dansk | |
| | N | Norsk | |
| | S | Svensk | |
| | GB | English | |
| | D | Deutsch | |
| | F | Francais | |
| | | | |
| Rengøring, pletfjerning | DK | Dansk | |
| | N | Norsk | |
| | S | Svensk | |
| | GB | English | |
| | D | Deutsch | |
| | F | Francais | |
| Producent | | | |
| Fabriks certificering | ISO 9001 | Audited and verified by BVC | |
| | ISO 14001 | Audited and verified by BVC | |
| | EMAS | Audited and verified by BVC | |

| Produktbeskrivelse | Metoder | Produktdata |
|---------------------------|----------------|----------------------------------|
| | DS/OHSAS | Audited and verified by BVC |
| | DS 49001 | Audited and verified by BVC |
| | CRuk | Member of Carpet Recycling UK |

ege

THE URGE TO EXPLORE SPACE